

Mike Massey

AIRCRAFT STATUS							
Maintenance Task	Inspection Freq.	C/W DATE	C/W TIME	Next Due	WARNING	DAYS REM.	
AIRCRAFT MODEL : BEECHCRAFT 300		AIRCRAFT REG # : N103AD		SN # :	FA-62		
L/H ENG. MOD/SN : PT6A-60 PC-E95132	R/H ENG. MOD/SN : PT6A-60 PC-E95131	TTAF :		6086			
L/H ENG.TTSN/OH: 6041.8 3017.2	R/H ENG.TTSN/OH: 6041.8 3049.7	TAFC :		5833			
L/H ENG.TCSN/OH: 6832 2603	R/H ENG.TCSN/OH: 7002 2655	HOBBS :		755			
L/H PROP MOD/SN : HC-B4MP-3B FWA2790	R/H PROP MOD/SN : HC-B4MP-3B FWA2793	DATE :		8/8/2008			
L/H PROP TTSN/OH : 6084.5 757.2	R/H PROP TTSN/OH : 6084.5 757.2						
AIRCRAFT TT			5331			6086	
AIRCRAFT BATTERY	3 Months	8/6/2008	N/A	11/5/2008		89	
WING FWD SPAR CAP	12 Months	1/22/2008	5714.8	1/20/2009		166	
ELT BATTERY FAR 91.207(D)	12 Months	8/31/2007	5913.7	8/29/2008		22	
WING BOLT LUBRICATION	12 Months	5/21/2008	6050.5	5/20/2009		286	
CABIN ALT. WARNING TEST	12 Months	5/21/2008	N/A	5/20/2009		286	
OXY. BARO. SWITCH	12 Months	5/21/2008	N/A	5/20/2009		286	
ELT BATTERY REPLACEMENT	24 Months	2/3/2007	N/A	2/1/2009		178	
PHASE 1	24 Months	4/9/2008	6032.8	4/8/2010		609	
PHASE 2	24 Months	4/9/2008	6032.8	4/8/2010		609	
PHASE 3	24 Months	4/9/2008	6032.8	4/8/2010		609	
PHASE 4	24 Months	4/9/2008	6032.8	4/8/2010		609	
IFR CERTIFICATION	24 Months	8/31/2007	5913.7	8/29/2009		387	
TRANS. CERTIFICATION	24 Months	8/31/2007	5913.7	8/29/2009		387	
PAX O2 VALVE	24 Months	8/6/2008	6086	8/5/2010		728	
L/H NACELLE FUEL PROBE	30 Months	5/21/2008	6050.5	11/19/2010		833	
R/H NACELLE FUEL PROBE	30 Months	5/21/2008	6050.5	11/19/2010		833	
AIRCRAFT WEIGHT & BALANCE	36 Months	8/9/2002	5714.8	8/7/2005	@@	-1097	
O2 CYL. 3HT LITE HYDO	36 Months	3/14/2008	6024.4	3/13/2011		947	
EDGELIGHTED PANEL INSP..	48 Months	8/9/2006	5714.8	8/7/2010		729	
L/H ENGINE FIRE EXT. CART.	48 Months	6/13/2005	5514.8	6/11/2009		307	
R/H ENGINE FIRE EXT. CART.	48 Months	6/13/2005	5514.8	6/11/2009		307	
L/H ENGINE FIRE EXT. HYDRO	60 Months	6/13/2005	5514.8	6/11/2010		672	
R/H ENGINE FIRE EXT. HYDRO	60 Months	6/13/2005	5514.8	6/11/2010		672	
BRAKE SYSTEM HOSES	60 Months	10/7/2004	5328.8	10/5/2009		423	
OXY. REG.	60 Months	10/7/2004	5328.8	10/5/2009		423	
L/H ENG FLAM. FLUID HOSE	60 Months	10/7/2004	5328.8	10/5/2009		423	
R/H ENG FLAM. FLUID HOSE	60 Months	10/7/2004	5328.8	10/5/2009		423	
WING BOLT INSPECTION	60 Months	2/20/2004	5125.8	2/17/2009		193	
L/H PROP OVERHAUL	60 Months	10/7/2004	8955.9	10/5/2009		423	
R/H PROP OVERHAUL	60 Months	10/7/2004	8955.9	10/5/2009		423	
L/H MLG SHOCK ASSY	72 Months	6/13/2005	5514.8	6/10/2011		1037	
DRAG BRACE, AXLE/TORQ KNEE	72 Months	6/13/2005	5514.8	6/10/2011		1037	
R/H MLG SHOCK ASSY	72 Months	6/13/2005	5514.8	6/10/2011		1037	
DRAG BRACE, AXLE/TORQ KNEE	72 Months	6/13/2005	5514.8	6/10/2011		1037	
NOSE GEAR SHOCK ASSY	72 Months	6/13/2005	5514.8	6/10/2011		1037	
DRAG BRACE, AXLE/TORQ KNEE	72 Months	6/13/2005	5514.8	6/10/2011		1037	
LDG. RET/EXT HOSES	120 Months	3/13/2005	5514.8	3/13/2015		2408	

Mike Massey

AIRCRAFT MODEL :	BEECHCRAFT 300	AIRCRAFT REG # :	N103AD	SN # :	FA-62
L/H ENG. MOD/SN	PT6A-60 PC-E95132	R/H ENG. MOD/SN	PT6A-60 PC-E95131	TTAF :	6086
L/H ENG.TTSN/OH:	6041.8 3017.2	R/H ENG.TTSN/OH:	6041.8 3049.7	TAFC :	5833
L/H ENG.TCSN/OH:	6832 2603	R/H ENG.TCSN/OH:	7002 2655	HOBBS :	755
L/H PROP MOD/SN	HC-B4MP-3B FWA2790	R/H PROP MOD/SN	HC-B4MP-3B FWA2793	DATE :	8/8/2008
L/H PROP TTSN/OH	6084.5 757.2	R/H PROP TTSN/OH	6084.5 757.2		

AIRCRAFT STATUS

Maintenance Task	Inspection Freq.	C/W DATE	C/W TIME	Next Due	WARNING	DAYS REM.
PILOT'S FIRE EXT	144	Months	8/9/2006	5714.8	8/3/2018	3648
CABIN FIRE EXT	144	Months	8/9/2006	5714.8	8/3/2018	3648
Maintenance Task	Inspection Freq.	C/W DATE	C/W TIME	Next Due	WARNING	TIME REM.
200 HOUR LUBRICATION	200	Hours	5/21/2008	6050.5	6250.5	164.5
400 HOUR LUBRICATION	400	Hours	5/21/2008	6050.5	6450.5	364.5
Forward Evaporator Filter	400	Hours	8/9/2006	6084.3	6484.3	398.3
Aft Evaporator Filter	400	Hours	8/9/2006	6084.3	6484.3	398.3
600 HOUR LUBRICATION	600	Hours	8/9/2006	5714.8	6314.8	228.8
INSTRUMENT AIR FILTER	600	Hours	8/9/2006	5714.8	6314.8	228.8
FUEL ACCESS PANAL	600	Hours	1/22/2008	5987	6587.0	501.0
WINDSHIELD ANTI-STATIC & SCREW TQ.	800	Hours	10/7/2004	5328.8	6128.8	42.8
800 HOUR LUBRICATION	800	Hours	5/21/2008	6050.5	6850.5	764.5
PHASE 1	800	Hours	4/9/2008	6032.8	6232.8	146.8
PHASE 2	800	Hours	4/9/2008	6032.8	6432.8	346.8
PHASE 3	800	Hours	4/9/2008	6032.8	6632.8	546.8
PHASE 4	800	Hours	4/9/2008	6032.8	6832.8	746.8
L/H STARTER GENERATOR	1000	Hours		5714.8	6714.8	628.8
R/H STARTER GENERATOR	1000	Hours		5328.8	6328.8	242.8
1200 HOUR LUBRICATION	1200	Hours	6/13/2005	5514.8	6714.8	628.8
PED. PWR LEVER STOP PIN	1200	Hours	6/13/2005	5514.8	6714.8	628.8
EDGE LIGHTED PANEL INSP.	2000	Hours	8/9/2006	5714.8	7714.8	1628.8
L/H NACELLE FUEL PROBE INSP.	2400	Hours	6/13/2005	5514.8	7914.8	1828.8
R/H NACELLE FUEL PROBE INSP.	2400	Hours	6/13/2005	5514.8	7914.8	1828.8
L/H PROP	3000	Hours	1/26/1902	5328.8	8328.8	2242.8
R/H PROP	3000	Hours	1/26/1902	5328.8	8328.8	2242.8
L/H Engine mount Vibration Isolators	4000	Hours		3067.3	7067.3	981.3
R/H Engine mount Vibration Isolators	4000	Hours		3035.3	7035.3	949.3

Mike Massey

AIRCRAFT MODEL :	BEECHCRAFT 300	AIRCRAFT REG # :	N103AD	SN # :	FA-62
L/H ENG. MOD/SN	PT6A-60 PC-E95132	R/H ENG. MOD/SN	PT6A-60 PC-E95131	TTAF :	6086
L/H ENG.TTSN/OH:	6041.8 3017.2	R/H ENG.TTSN/OH:	6041.8 3049.7	TAFC :	5833
L/H ENG.TCSN/OH:	6832 2603	R/H ENG.TCSN/OH:	7002 2655	HOBBS :	755
L/H PROP MOD/SN	HC-B4MP-3B FWA2790	R/H PROP MOD/SN	HC-B4MP-3B FWA2793	DATE :	8/8/2008
L/H PROP TTSN/OH	6084.5 757.2	R/H PROP TTSN/OH	6084.5 757.2		

AIRCRAFT STATUS

Maintenance Task	Inspection Freq.	C/W DATE	C/W TIME	Next Due	WARNING	CYC. REM.
LDG HYD. SYS. FILTER	1200	Cycles	5/13/2003	4928	6128	295
CABIN,CARGO & EMERG EXIT	1000	Cycles	5/13/2003	4928	5928	95
L/H MLG ACT. CLEVIS HOLE	1000	Cycles	6/13/2005	5515	6515	682
R/H MLG ACT. CLEVIS HOLE	1000	Cycles	6/13/2005	5515	6515	682
NOSE GEAR ACT. CLEVIS HOLE	1000	Cycles	6/13/2005	5515	6515	682
Forward Pressure Bulkhead Insp.	2500	Cycles		5787	8287	2454
R/H FLAP FLEX SHAFT	5000	Cycles	5/13/2003	4928	9928	4095
L/H FLAP FLEX SHAFT	5000	Cycles	5/13/2003	4928	9928	4095
CABIN DOOR & FUSE FRAME	5000	Cycles	5/13/2003	4928	9928	4095
CABIN DOOR FWD/AFT BOLTS	5000	Cycles	5/13/2003	4928	9928	4095
Upper & Lower windsheild conners	10000	Cycles				
Cabin door and fuselage frame	10000	Cycles				
Exterior Skin inspection	10000	Cycles				
Fulslage frame FS143-FS382	10000	Cycles				
Frame Web FS179-FS271	10000	Cycles				
Stringer from Web FS179-FS271	10000	Cycles				
Flight controls brackets and casting	10000	Cycles				
Aft fuselage area and pressure bulkhead	10000	Cycles				

ENGINE STATUS

L/H P3 filter replacement	1000	Hours		5125.8	6125.8	39.8
R/H P3 filter replacement	1000	Hours		5125.8	6125.8	39.8
L/H oil filter replacement	1000	Hours		5125.8	6125.8	39.8
R/H oil filter replacement	1000	Hours		5125.8	6125.8	39.8
L/H engine overhaul	3600	Hours		3067.3	6667.3	581.3
L/H engine overhaul	3600	Hours		3035.3	6635.3	549.3
L/H engine fuel nozzle	400	Hours		5714.8	6114.8	28.8
L/H engine fuel nozzle	400	Hours		5714.8	6114.8	28.8
L/H Engine HSI	1800	Hours		4680.4	6480.4	394.4
R/H Engine HIS	1800	Hours		4647.1	6447.1	361.1

Recurring AD's and MSB

AD 89-19-04R1/SB2040R3 WING PANALS	600	Hours	4/28/2006	5680.8	6280.8	195
MSB 27-3459 GUST LOCK INSP	12	Months	5/21/2008	6050.5	5/20/2009	286
MSB 27-3549 GUST LOCK INSP	200	Hours	5/21/2008	6050.5	6250.5	165
AD 05-01-18/MSB 53-2472R4 AFT STRING. INS	500	Cycles	5/21/2008	5833	6333	500

Vectair usa

AIRCRAFT MODEL :	BEECHCRAFT 300	AIRCRAFT REG # :	N103AD	SN # :	FA-62
L/H ENG. MOD/SN	PT6A-60 PC-E95132	R/H ENG. MOD/SN	PT6A-60 PC-E95131	TTAF :	6086
L/H ENG.TTSN/OH:	6041.8 3017.2	R/H ENG.TTSN/OH:	6041.8 3049.7	TAFC :	5833
L/H ENG.TCSN/OH:	6832 2603	R/H ENG.TCSN/OH:	7002 2655	HOBBS :	755
L/H PROP MOD/SN	HC-B4MP-3B FWA2790	R/H PROP MOD/SN	HC-B4MP-3B FWA2793	DATE :	8/8/2008
L/H PROP TTSN/OH	6084.5 1/26/1902	R/H PROP TTSN/OH	6084.5 1/26/1902		

AIRFRAME AIRWORTHINESS DIRECTIVES

Maintenance Task	Compliance	Last C/W	C/W TIME	Next Due	AP/IA #	SIGN.
80-07-05 Lwr Fwd Wing Bolt Assy.	N/A	1/26/1980		N/A	3007963 AP	Kyle Peterson
80-09-03 Oxygen control cable	PCW	8/29/1980		N/A	3007963 AP	Kyle Peterson
83-07-04 one ply window failure	N/A BY SN	N/A	N/A	N/A	3007963 AP	Kyle Peterson
84-24-01 superceded by 87-17-05	SUPERCEDED	N/A	N/A	N/A	3007963 AP	Kyle Peterson
85-22-05 Outer wing panals inspection	N/A INCONEL BOLTS	N/A	N/A	N/A	3007963 AP	Kyle Peterson
86-20-03 superceded by 87-04-24	SUPERCEDED	N/A	N/A	N/A	3007963 AP	Kyle Peterson
87-04-24 elevator trim sys. Malfunction	C/W BY MOD OF ELEV TRIM PER SB2028R3	6/4/1987	4044.5	N/A	3007963 AP	Kyle Peterson
87-17-05 superceded by 89-19-04	SUPERCEDED	12/3/1987		N/A	3007963 AP	Kyle Peterson
87-22-01 R1 Nose gear fork insp.	SUPERCEDED BY AD 04-23-02	35965.0	7297.8	N/A	3007963 AP	Kyle Peterson
89-19-04 R1 wing fuel bay upper skin failure	N/A	N/A	N/A	N/A	3007963 AP	Kyle Peterson
89-22-14 aileron flutter	N/A	N/A	N/A	N/A	3007963 AP	Kyle Peterson
90-08-17 Aft fuselage drains	C/W PER SB 2312	3/7/1990		N/A	3007963 AP	Kyle Peterson
91-12-11 cast acrylic windows	C/W PER SB 2208R1	12/11/1991	5401.0	N/A	3007963 AP	Kyle Peterson
91-18-11 superceded by 92-10-12	SUPERCEDED	12/11/1991	5401.0	N/A	3007963 AP	Kyle Peterson
92-10-12 seperation of aft cowl doors	C/W PER SB 2416R1	12/11/1991	5401.0	N/A	3007963 AP	Kyle Peterson
92-15-01 Engine truss mount bolts	C/W PER SB 2432	3/12/1992		N/A	3007963 AP	Kyle Peterson
92-27-10 Superceded by 97-06-06	SUPERCEDED	11/2/1995		N/A	3007963 AP	Kyle Peterson
93-25-07 aft fuselage stringers	SUPERCEDED BY AD 05-01-18	9/3/2004	8926.8	N/A	3007963 AP	Kyle Peterson
95-13-03 ldg motor circuit braker	C/W PER SB 2035R3	2/25/1998		N/A	3007963 AP	Kyle Peterson
96-03-13 Ldg.drag leg failure	C/W PER SB 2607R1	5/14/1996	6799.7	N/A	3007963 AP	Kyle Peterson
96-09-13C Ops in icing cond.	C/W BY POH REV.	9/17/1998	7382.1	N/A	3007963 AP	Kyle Peterson
97-06-06 C Pilot & co-pilots chair inadvertent move	C/W PER SB 2444R2	5/5/1997		N/A	3007963 AP	Kyle Peterson
97-23-17 loss of vacumn	C/W PER SB 2676	8/17/1998	7346.7	N/A	3007963 AP	Kyle Peterson
97-25-01 Outflow/safety valve insp.	N/A PER SN	2/25/1998	7205.2	N/A	3007963 AP	Kyle Peterson
97-25-03 Afm supliment, nose down pitch	C/W BY POH REV.	8/17/1998	7346.7	N/A	3007963 AP	Kyle Peterson
98-10-05 Eng. Fire detection	N/A PER SN	N/A	N/A	N/A	3007963 AP	Kyle Peterson

Vectair usa

AIRCRAFT MODEL :	BEECHCRAFT 300	AIRCRAFT REG # :	N103AD	SN # :	FA-62
L/H ENG. MOD/SN	PT6A-60 PC-E95132	R/H ENG. MOD/SN	PT6A-60 PC-E95131	TTAF :	6086
L/H ENG.TTSN/OH:	6041.8 3017.2	R/H ENG.TTSN/OH:	6041.8 3049.7	TAFC :	5833
L/H ENG.TCSN/OH:	6832 2603	R/H ENG.TCSN/OH:	7002 2655	HOBBS :	755
L/H PROP MOD/SN	HC-B4MP-3B FWA2790	R/H PROP MOD/SN	HC-B4MP-3B FWA2793	DATE :	8/8/2008
L/H PROP TTSN/OH	6084.5 1/26/1902	R/H PROP TTSN/OH	6084.5 1/26/1902		

RAYTHEON MANDATORY SERVICE BULLETINS

	Maintenance Task	Compliance	C/W DATE	C/W TIME	Next Due	AP/IA #	SIGN.
11-2238	Inst. Of gear service placard	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
21-2481R1 97-25-01	Outflow/safety valve failure	C/W BY INSP	2/25/1998	7205.2	N/A	3007963 AP	Kyle Peterson
21-2676 97-23-17	Pneumatic tubing insp	C/W BY INSP & REPAIR	8/17/1998	7346.7	N/A	3007963 AP	Kyle Peterson
21-2681	Aircond. Relief valve installation	C/W BY INST.KIT	12/16/1998	2438.9	N/A	3007963 AP	Kyle Peterson
22-2283R2	Install of autopilot servo covers	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
22-2388	Autopilot trim fail wiring mod.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
22-2423 92-06-11	Mod. Of flight inst. & APS-65H	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
22-2603	Replacemnt of KAM 432 autopilot	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
22-3180R1	Bendix/King/Dot-Auto flight	N/A NOT EQUIPT	9/30/1998	7361.4	N/A	3007963 AP	Kyle Peterson
24 2035R3 95-13-03	Ldg. Motor control	INSTALLED CIRCUIT BREAKER	2/25/1998		N/A	3007963 AP	Kyle Peterson
25-2057R2	Shoulder harness kits	N/A BY S/N	2/25/1998		N/A	3007963 AP	Kyle Peterson
2213R3	Insp. of pilot & co-pilots seat tracks	N/A MOVED TO INSP. MANUAL	11/20/1992		N/A	3007963 AP	Kyle Peterson
25-2032R2	Shoulder harness kits	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
25-2444R2 97-06-06	Pilot / co-pilot chair locking mech insp	C/W BY MOD. PILOT & COPILOTS SEATS	11/2/1995 5-05-97		N/A	3007963 AP	Kyle Peterson
25-2598R2	ELT placard installation	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
25-3418	Remove placard on Artex ELT 110	N/A BY P/N INST.			N/A	3007963 AP	Kyle Peterson
26-2005R1	Relocation of eng, fire detectors	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
26-2701 98-10-05	FIRE PROTECTOR	N/A BY S/N	9/17/1998		N/A	3007963 AP	Kyle Peterson
27-2028R4 87-04-24	FLIGHTCONTROL ELEVATOR TRIM	C/W ELEV. TRIM TAB INSP.	7/16/1984		N/A	3007963 AP	Kyle Peterson
27-2150 R2	Elevator pulley brackets	PCW	2/13/1996	6783.8	N/A	3007963 AP	Kyle Peterson
27-2212	Cable tensions					3007963 AP	Kyle Peterson
27-3038	RUDDER TORQUE SHAFT	C/W BY INSP.			N/A	3007963 AP	Kyle Peterson
27-3187 02-23-11	ELEVATOR WT. ADJ.	C/W BY MOD OF ELEVATORS			N/A	3007963 AP	Kyle Peterson

Vectair usa

AIRCRAFT MODEL :	BEECHCRAFT 300	AIRCRAFT REG # :	N103AD	SN # :	FA-62
L/H ENG. MOD/SN	PT6A-60 PC-E95132	R/H ENG. MOD/SN	PT6A-60 PC-E95131	TTAF :	6086
L/H ENG.TTSN/OH:	6041.8 3017.2	R/H ENG.TTSN/OH:	6041.8 3049.7	TAFC :	5833
L/H ENG.TCSN/OH:	6832 2603	R/H ENG.TCSN/OH:	7002 2655	HOBBS :	755
L/H PROP MOD/SN	HC-B4MP-3B FWA2790	R/H PROP MOD/SN	HC-B4MP-3B FWA2793	DATE :	8/8/2008
L/H PROP TTSN/OH	6084.5 1/26/1902	R/H PROP TTSN/OH	6084.5 1/26/1902		

RAYTHEON MANDATORY SERVICE BULLETINS

Maintenance Task	Compliance	C/W DATE	C/W TIME	Next Due	AP/IA #	SIGN.
27-3232 99-09-15 CONTROL COLUMN INTER.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
27-3459 Flight control gust lock insp / repl	CW BY INSP.	5/7/2004	8765.2	8965.2	3007963 AP	Kyle Peterson
27-3492 CONTROL COLUMN INSP.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
27-3668R1 Insp. Of aileron outbd. Hinge	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
28-2718R2 05-01-04 Repl of MILH6000B hose mfg by Buckeye	CW BY INSP.& REPL OF HOSES	9/17/1998	7382.1	N/A	3007963 AP	Kyle Peterson
32-2046 LDG MOD POWER TIME DELAY	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-2102R7 04-23-02 Nose gear lwr shock absorb assy insp	C/W NEW NOSE FORK INST.	6/19/1998		N/A	3007963 AP	Kyle Peterson
32-2220 Nose landing gear steering link insp/repl	C/W BY INSP.	2/1/1996	6775.8	N/A	3007963 AP	Kyle Peterson
32-2226R2 LDG. POWER PACK MOTOR RELAY	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-2386 LDG ACT. ALLEN MFG.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-2607R1 96-03-13 Main landing gear drag leg lock link insp	C/W BY INSP.	5/14/1996	6799.7	N/A	3007963 AP	Kyle Peterson
32-2658R2 Ldg. Gear act. Support brkt.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-2728R1 Ldg. Gear act. Clevis repl.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-3073R1 99-09-10 LDG HAND PUMP FILTER	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-3340 LDG HYD. PUMP REPL.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
32-3433R1 Mlg. gear reract act nut assy replacement	C/W BY REPL. OF ACT. NUTS			N/A	3007963 AP	Kyle Peterson
32-3682 Mlg piston assy.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
34-2294R1 COLLINS MCS-65	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
34-3269R1 01-11-03 K33 BLOWER FUSE	N/A BY S/N	3/24/1999		N/A	3007963 AP	Kyle Peterson
34-3355 STATIC AIR DATA FLAG	N/A NOT EQUIPT			N/A	3007963 AP	Kyle Peterson
34-3435 TDR94/94D TRANSPONDER	N/A NOT EQUIPT			N/A	3007963 AP	Kyle Peterson

Vectair usa

AIRCRAFT MODEL :	BEECHCRAFT 300	AIRCRAFT REG # :	N103AD	SN # :	FA-62
-------------------------	----------------	-------------------------	--------	---------------	-------

L/H ENG. MOD/SN	PT6A-60	PC-E95132	R/H ENG. MOD/SN	PT6A-60	PC-E95131	TTAF :	6086
L/H ENG.TTSN/OH:	6041.8	3017.2	R/H ENG.TTSN/OH:	6041.8	3049.7	TAFC :	5833
L/H ENG.TCSN/OH:	6832	2603	R/H ENG.TCSN/OH:	7002	2655	HOBBS :	755
L/H PROP MOD/SN	HC-B4MP-3B	FWA2790	R/H PROP MOD/SN	HC-B4MP-3B	FWA2793	DATE :	8/8/2008
L/H PROP TTSN/OH	6084.5	1/26/1902	R/H PROP TTSN/OH	6084.5	1/26/1902		

RAYTHEON MANDATORY SERVICE BULLETINS

Maintenance Task	Compliance	C/W DATE	C/W TIME	Next Due	AP/IA #	SIGN.
35-3020 PAX OXY. MASKS	C/W BY INSP.			N/A	3007963 AP	Kyle Peterson
52-3096R1 Ext door operating instruct placard	C/W BY INST. PLACARD	4/4/2003	8346.4	N/A	3007963 AP	Kyle Peterson
53-2312 Aft fuselage moisture drain system insp	C/W BY INSP.	3/7/1990	4975.8	N/A	3007963 AP	Kyle Peterson
53-2472R4 AFT STRINGER INSP. O5-01-18	C/W BY INSP.	9/3/2004	8926.8	9426.8	3007963 AP	Kyle Peterson
53-3400R1 WING TO FUS. FUEL WIRING	N/A	7/21/2003	8480.3	N/A	3007963 AP	Kyle Peterson
53-3513R1 Aft press bulkhead web insp / repair O3-13-16	C/W BY INSP.	12/31/2003	8608.2	N/A	3007963 AP	Kyle Peterson
55-3403R1 HORI. STAB INSP.	INACTIVE			N/A	3007963 AP	Kyle Peterson
55-2254R1 HORIZONTAL STAB SEALING	C/W BY SEALING	2/25/1998		N/A	3007963 AP	Kyle Peterson
55-2422R1 RUDDER TORQUE SHAFT 92-06-11	C/W BY MODIFYING	5/14/1996	6799.7	N/A	3007963 AP	Kyle Peterson
56-2208R1 WINDOWS INSP. 91-12-11	C/W BY REPLACEMENT OF WINDOWS	12/11/1991	5401.0	N/A	3007963 AP	Kyle Peterson
57-2040R3 WING PANAL INSP. 89-19-04	N/A BY S/N	10/8/1987		600.0	3007963 AP	Kyle Peterson
57-2240 Wing spar repl.	N/A BY S/N			N/A	3007963 AP	Kyle Peterson
57-2256 WINGS 89-22-14	C/W BY REMOVAL OF SCOTH FOAM			N/A	3007963 AP	Kyle Peterson
61-2266R1 Hartzell sb 159	C/W BY INST. PLACARD			N/A	3007963 AP	Kyle Peterson
61-3737 Prop mount bolt insp.					3007963 AP	Kyle Peterson
71-2416R1 ENG. COWL MOD 92-10-12	C/W BY MODIFYING			N/A	3007963 AP	Kyle Peterson
71-2432 Engine mount assy insp 92-15-01	C/W BY REPL. OF ENG. MTS.	3/12/1992	5454.9	N/A	3007963 AP	Kyle Peterson
73-3634 Replace existing bolts with drilled bolts O4-17-02	C/W PEDESTALL SHAFT BOLT REPL.	8/27/2004	8918.0	N/A	3007963 AP	Kyle Peterson

